



TOYOTA Avensis: 1FWD797			
Vinnnumber:	SB1ED76L40E115700	Versionname:	AVENSIS WAG Comfort DPF 124PK
First Registrationdate:	15/11/2013	Fiscalpower:	
Expertise Mileage:	121783	Power Kw:	91
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2114
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	215/55/17/98 V LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1156,65
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)			95,00



Rocker panel inner R R, Scratch(es), Acceptable	0,00
--------------------------------------------------------	-------------

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00




Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

