



BMW 3: 1GHF467

Vinnnumber:	WBA3D11020J625996	Versionname:	3 BER 318d 136PK
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	54537	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3615
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			635,56
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80





Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Sill outer R, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display