


BMW 1: 1FGU439

Vinnumber:	WBA1C91020J513286	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	25/06/2013	Fiscalpower:	
Expertise Mileage:	162552	Power Kw:	85
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3427
Maintenance:	DANS 11000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	673,00
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearlight L, Damaged, Acceptable	0,00
----------------------------------	------



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover R L, Scratch(es), Acceptable 0,00



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display