



BMW 3: 1GCN995			
Vinnumber:	<b>WBA3D110X0J625292</b>	Versionname:	<b>3 BER 318d 136PK</b>
First Registrationdate:	<b>2/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>86929</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3833</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
GPS storage	
GPS storage	<b>HD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
Adaptive cruise control	

Limited Technical Inspection			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

Degree of wear				
	<b>235/50/17/94 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

Assistance equipment	
Runflat	<b>Yes</b>

Total cost ex VAT	<b>481,50</b>
Roof, Chemical polution, LI - Repair and paint (complete)	<b>481,50</b>



Wing R L, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bonnet, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door R R, Bump(s), Acceptable	<b>0,00</b>

<i>No pictures to display</i>	
Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	