


BMW 1: 1GHM437

Vinnumber:	WBA1C11070VU94504	Versionname:	1 BER HATCH 118d 136PK
First Registrationdate:	10/02/2014	Fiscalpower:	
Expertise Mileage:	95899	Power Kw:	100
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2629
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/45/17/91 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		118,19
Door R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), 67 - Polish		55,19
<i>No pictures to display</i>		
Rear spoiler, Scratch(es), Acceptable		0,00



Mirror side blinker L, Broken, Acceptable

0,00




Door R R, Scratch(es), Acceptable 0,00

No pictures to display


Seat cover F L, Stain, Cleaning 0,00



Door R L, Bump(s), PDR - Knock out without painting 63,00



Tailgate, Scratch(es), Acceptable 0,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bump(s), Acceptable 0,00

No pictures to display

Alloy Rims (all), Scratch(es), I - Repair 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display