



## CITRO?N C4 Picasso: 1JNP115

Vinnnumber:	<b>VF73AAHRMEJ843776</b>	Versionname:	<b>GR.C4 PICASSO BlueHDi Exclusive 150PK</b>
First Registrationdate:	<b>26/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>55417</b>	Power Kw:	<b>110</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3625</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L	
GPS storage	<b>HD</b>	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

## Degree of wear

	<b>205/55/17/95 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

## Assistance equipment















Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 987,14

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

			Rearlight R , Waterinfiltration, Acceptable	0,00
			Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Front bumper, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Door F L, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Door R R, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Bonnet, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Maintenance book, Missing, E - Replace				0,00
<i>No pictures to display</i>				
Engine protective plate, Deformed, Acceptable				0,00
				
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)				95,00
			Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Wing R L, Stain, Acceptable				0,00
<i>No pictures to display</i>				
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)				95,00
			Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Wing F L, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Rearlight L, Stain, Acceptable				0,00
			Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Rearlight L, Scratch(es), 67 - Polish

55,19

