



CITROEN C4 Picasso: 1DXC817

Vinnnumber:	VF7UD9HR8CJ695502	Versionname:	PICASSO.e-HDi Bus.GPS
First Registrationdate:	24/09/2012	Fiscalpower:	FAP BMP 112PK Aut
Expertise Mileage:	179499	Power Kw:	82
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3226
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	258,80
-------------------	--------

Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bodywork, Not original part, Remove lettering	50,00
---	-------



Maintenance, Maintenance, P - Check 0,00



Steering wheel, Worn, Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, P - Check 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Moulding windscreen R, Stone chip(s), Acceptable 0,00

No pictures to display

Moulding windscreen L, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display

Ignition key, Damaged, E - Replace 150,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Stone chip(s), Acceptable 0,00

No pictures to display