


FORD Mondeo: 1EBU818

Vinnnumber:	WFOEXXGBBECL55985	Versionname:	MONDEO BER Econetic Titanium 115PK
First Registrationdate:	15/10/2012	Fiscalpower:	
Expertise Mileage:	107445	Power Kw:	85
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1332
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/45/17/94 V LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	713,70
-------------------	--------

Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------




No pictures to display

Bumper corner R R, Scratch(es), It - Spot repair	0,00
--	------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
	
Wing R L, Scratch(es), Acceptable	0,00
	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper cover R M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, P - Check	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rear spoiler, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Mirror side blinker R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	