


FORD Focus: 1GNU631

Vinnnumber:	WF0LXXGCBLES16854	Versionname:	FOCUS CLIP. ECONetic Titanium 88g 105PK
First Registrationdate:	20/03/2014	Fiscalpower:	
Expertise Mileage:	191869	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	478,76
-------------------	--------

Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display





Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Scratch(es), I I - Repair and paint (complete)	308,20
--	--------

			Wing F L, Scratch(es), LI - Repair and paint (complete)	0,00
Interior, Dirty, Cleaning				25,00
			Trunk lid covering R, Scratch(es), Acceptable	0,00
			Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Tailgate, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Rear spoiler, Scratch(es), LI - Repair and paint (complete)				115,56

			Windscreen, Crack, E - Replace	0,00
---	---	--	--------------------------------	------

