



FORD Grand C-Max: 1EPB416

| | | | |
|-------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber: | WF0HXXWPBHDJ68457 | Versionname: | GR.C-MAX Trend St/St |
| First Registrationdate: | 12/02/2013 | Fiscalpower: | 95PK |
| Expertise Mileage: | 59331 | Power Kw: | 70 |
| Bodytype: | MPV | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3404 |
| Number of doors: | 5 | | |
| Number of seats: | 4 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|--------------------------------|-------------------------------|----------------------|--|
| Radio CD | | Luggage cover | |
| GPS storage | SD | Rear parking sensors | |
| GPS storage | | | |
| Windows electric F | | | |
| Windows electric R | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------------|-------|----------------------------|
| | 215/55/16/93 H LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 6,5 mm | Fr.R. | Bridgestone: 6,5 mm |
| | Re.L. | Uniroyal: 7 mm | Re.R. | Uniroyal: 7 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 285,20 |
|-------------------|--------|




| | |
|-------------------------------------|--------|
| Alloy rim F R, Damaged, E - Replace | 235,20 |
|-------------------------------------|--------|



| | |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|--------------------------------------|------|
| Rear window, Scratch(es), Acceptable | 0,00 |
|--------------------------------------|------|

| | |
|--|-------|
| Rear window, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Ignition key, Not functioning (well), P - Check | 0,00 |
|  | |
| Door R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Interior, Dirty, Cleaning | 50,00 |
|  | |
|  | |
| Tailgate, Bad repair, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |