


BMW 1 HATCH: 1LFE016

Vinnumber:	WBA1V910305B19236	Versionname:	1.5 116D
First Registrationdate:	11/09/2015		EFFICIENTDYNAMICS
Expertise Mileage:	52349		EDIT. (85KW)
Bodytype:	Hatchback	Fiscalpower:	
Gearbox:	MAN 6 VIT	Power Kw:	85
Transmission:	Back	Body color	Dark Grey
Fueltype:	Diesel	Paint type	Metalic
Battery functioning	Yes	Rims summer	Aluminium
Number of doors	5	Oil level	OK
Number of seats	5	Parking lot	1605
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection


Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			993,56
Alloy rim R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00
--	--	--	-------



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08

