


FORD Mondeo: 1CJP794

Vinnumber:	WFOGXXGBBGBP28701	Versionname:	MONDEO CLIP Titanium
First Registrationdate:	13/12/2011	Fiscalpower:	136PK
Expertise Mileage:	103873	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2431
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 7 mm	Re.R.	Fulda: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	306,80
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Gear shift lever cover, Worn, Acceptable	0,00



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

no pictures to display

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display