



AUDI A3: 1GKX449			
Vinnnumber:	WAUZZZ8VXE124664	Versionname:	A3 SB Ambiente 105PK
First Registrationdate:	6/03/2014	Fiscalpower:	
Expertise Mileage:	118078	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2412
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
GPS storage	SD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			875,28
Rear spoiler, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L, Damaged, E - Replace			235,20





Engine protective plate, Hole, E - Replace 77,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display


Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Damaged, E - Replace 83,00



Seat cover F L, Worn, Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar L, Stone chip(s), Acceptable 0,00

No pictures to display

Roof, Scratch(es), Acceptable 0,00

No pictures to display