



**MERCEDES E BERLINE: 1JHL945**

Vinnumber:	<b>WDD2120061B126964</b>	Versionname:	<b>2.1 E 200 BLUETEC</b>
First Registrationdate:	<b>22/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>74947</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1127</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

<b>245/45/17/95 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 1 mm</b>	Re.R.	<b>Michelin: 1 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------





Total cost ex VAT 1233,88

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable

0,00

<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Rearview mirror basis R, Scratch(es), Smart repair		110,64
		
Sill outer R, Scratch(es), LI - Repair and paint (complete)		372,60
		
Windscreen, Damaged, E - Replace		560,64
		
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		