



AUDI A3: 1GCX759

Vinnumber:	WAUZZZ8V3EA114851	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	172956	Power Kw:	77
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2528
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	240,00
-------------------	---------------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Damaged, E - Replace 240,00



Door R L, Bump(s) and scratch(es), Le - Replace and paint 0,00



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display