



<b>HYUNDAI i20: 1RKG940</b>			
Vinnnumber:	<b>NLHB251PAHZ258192</b>	Versionname:	<b>i20 5 doors V5b - 1.1 D M6</b>
First Registrationdate:	<b>11/01/2017</b>	Fiscalpower:	<b>75 - Air</b>
Expertise Mileage:	<b>12941</b>	Power Kw:	
Bodytype:		Body color	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1325</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

<b>Options</b>	
Windows electric F	Luggage cover
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>185/65/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>363,88</b>
Front bumper, Scratch(es), LI - Repair and paint (complete)			<b>169,44</b>



Wing R L, Scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Bumper R, Scratch(es), LI - Repair and paint (complete)		<b>169,44</b>



Seat cover F R, Stain, Cleaning 25,00



Door R R, Scratch(es), Acceptable 0,00

