



**AUDI A3: 1GGK936**

Vinnumber:	<b>WAUZZ8V2EA121418</b>	Versionname:	<b>Attraction 105PK</b>
First Registrationdate:	<b>3/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>100841</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3213</b>
Maintenance:	<b>SERVICE OVER 200 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
TV/DVD screen F	Luggage cover
GPS storage	<b>SD</b> Front parking sensors
GPS storage	Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	<b>Tow bar removable</b>
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 6 mm</b>	Fr.R.	<b>Kleber: 6 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>231,12</b>
-------------------	---------------

Front bumper, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Maintenance, Maintenance, P - Check	<b>0,00</b>
-------------------------------------	-------------



Sill outer L, Bump(s), It - Spot repair

115,56

