



**MERCEDES B: 1GEE075**

|                                    |                          |              |                                  |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber:                         | <b>WDD2462121J234426</b> | Versionname: | <b>B 180CDI BE Edition 109PK</b> |
| First Registrationdate:            | <b>14/01/2014</b>        | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>171585</b>            | Power Kw:    | <b>80</b>                        |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                     |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1224</b>                      |
| Number of doors:                   | <b>5</b>                 |              |                                  |
| Number of seats:                   | <b>5</b>                 |              |                                  |
| Number head rests:                 | <b>5</b>                 |              |                                  |
| Rims summer:                       | <b>Steel</b>             |              |                                  |
| Category:                          | <b>Passenger Car</b>     |              |                                  |
| Oil level:                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                  |

**Options**

|                                |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Central consol F              |
| GPS storage                    | Luggage cover                 |
| GPS storage                    | <b>HD</b>                     |
| Windows electric F             |                               |
| Windows electric R             |                               |
| Steering wheel multifunctional |                               |
| Radio multimedia               |                               |
| Type of headlighting           | <b>Headlighting Halogen</b>   |
| Type of GPS                    | <b>GPS big screen color</b>   |
| Type of Lining                 | <b>Lining fabrics</b>         |
| Type of climate control        | <b>Manual climate control</b> |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

**Degree of wear**

|               |                             |                         |       |                         |
|---------------|-----------------------------|-------------------------|-------|-------------------------|
|               | <b>195/65/15/91 T Steel</b> |                         |       |                         |
| Winter tyres: | Fr.L.                       | <b>Vredestein: 6 mm</b> | Fr.R. | <b>Vredestein: 6 mm</b> |
|               | Re.L.                       | <b>Michelin: 6 mm</b>   | Re.R. | <b>Michelin: 6 mm</b>   |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |               |
|---|---------------|
| Total cost ex VAT                                       | <b>530,15</b> |
| Door R R, Scratch(es), LI - Repair and paint (complete) | <b>318,35</b> |



|   |               |
|---|---------------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b> |
|---|---------------|



|  |      |
|--|------|
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>            |      |
| Roof pillar R, Bump(s), Acceptable       | 0,00 |
| <i>No pictures to display</i>            |      |
| Door F R, Bump(s), Acceptable            | 0,00 |
| <i>No pictures to display</i>            |      |
| Door panel R L, Scratch(es), Acceptable  | 0,00 |
| <i>No pictures to display</i>            |      |
| Wheel cover F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>            |      |
| Bumper R, Scratch(es), Acceptable        | 0,00 |
| <i>No pictures to display</i>            |      |