



## AUDI A4: 1GCV703

Vinnumber:	<b>WAUZZZ8K9EN019581</b>	Versionname:	<b>A4 BER TDie 136PK</b>
First Registrationdate:	<b>3/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>147875</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 2100 KM 303 J</b>	Parking lot:	<b>1308</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
GPS storage	Rear parking sensors
GPS storage	<b>DVD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

## Limited Technical Inspection

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

## Degree of wear

	<b>205/60/16/96 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	731,80
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

*No pictures to display*

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

