


**OPEL Zafira: 1E0S131**

Vinnumber:	<b>WOLPD9EL0D2032207</b>	Versionname:	<b>2.0 D TOURER Enjoy 110PK</b>
First Registrationdate:	<b>8/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>107870</b>	Power Kw:	<b>81</b>
Bodytype:		Body color	<b>Met.</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>Black</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Steel</b>
Maintenance	<b>OK</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2201</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>SD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/50/17/94 H Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	417,21
-------------------	--------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper spoiler F, Scratch(es), E - Replace	42,00
--	-------



Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Engine, Tear, E - Replace	91,45
---------------------------	-------



Wing R L, Bump(s), PDR - Knock out without painting 63,00



Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Bump(s), Acceptable 0,00

*No pictures to display*

Wing R L, Scratch(es), 67 - Polish 55,19



Wheel cover F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Scratch(es), 67 - Polish 55,19



Door R L, Scratch(es), 67 - Polish 55,19



Wing F R, Scratch(es), 67 - Polish 55,19



Step L, Scratch(es), Acceptable 0,00

*No pictures to display*