



**PEUGEOT 308: 1FHM042**

Vinnumber:	<b>VF34C9HP0DS074495</b>	Versionname:	<b>308 BER Active 92PK</b>
First Registrationdate:	<b>1/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>151049</b>	Power Kw:	<b>68</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3533</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1389,64
-------------------	---------

Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*






Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	502,50
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
		
Front bumper, Bad repair, Paint		0,00
		
Roof, Chemical polution, LI - Repair and paint (complete)		481,50
		
Seat cover F L, Deformed, Acceptable		0,00
		
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)		115,56
		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		