



PEUGEOT Partner: 1BCV402

Vinnnumber:	VF37A9HTCBJ516450	Versionname:	PARTNER B/F L1H1 P.CD-Airco 120 75PK
First Registrationdate:	4/05/2011	Fiscalpower:	
Expertise Mileage:	185196	Power Kw:	55
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3414
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Dunlop: 6,5 mm	Fr.R.	Dunlop: 6,5 mm
	Re.L.	Dunlop: 6,5 mm	Re.R.	Dunlop: 6,5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	945,42
--------------------------	---------------

Windscreen, Crack, E - Replace	395,40
---------------------------------------	---------------



Trunk door panel R, Damaged, E - Replace	69,00
---	--------------



Steering wheel, Worn, Acceptable	0,00
---	-------------



Trunk door panel L, Damaged, E - Replace 69,00



Roof, Bump(s), Acceptable 0,00



Interior, Stain, Cleaning 50,00



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Trunk door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 362,02



Gear shift lever cover, Worn, Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display