


PEUGEOT 308: 1GGL269

Vinnnumber:	VF3LB9HPAES008002	Versionname:	308 BER Active 92PK
First Registrationdate:	3/02/2014	Fiscalpower:	
Expertise Mileage:	111486	Power Kw:	68
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3719
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment









Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	618,99
-------------------	--------

Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Door panel R R, Hole, E - Replace	114,00
-----------------------------------	--------

	Rearlight L, Scratch(es), 67 - Polish	55,19
	Seat cover F L, Stain, Cleaning	25,00
	Door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>		
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)		95,00
	Handbreak cover, Worn, Acceptable	0,00
	Engine protective plate, Tear, E - Replace	55,00
	Wing R L, Bump(s), PDR - Knock out without painting	63,00
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Front bumper, Not original part, Acceptable	0,00
<i>No pictures to display</i>		
Door F R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		