



RENAULT Master 35 L3H1: 1DKD535			
Vinnnumber:	<b>VF1MAF4DE47272632</b>	Versionname:	<b>MASTER 35 B/F L3H2 Gr.conf.(E5)125PK</b>
First Registrationdate:	<b>7/06/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>65687</b>	Power Kw:	<b>92</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV31</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Rear parking sensors
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

Limited Technical Inspection			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

Degree of wear				
	<b>225/65/16/112 R Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Fulda: 4 mm</b>	Re.R.	<b>Fulda: 4 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			2010,95
De-icer nozzle internal L, Broken, E - Replace			153,00



Bumper corner R L, Damaged, Smart repair	110,64
--	--------



Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Seat cover F L, Hole, E - Replace	300,00
-----------------------------------	--------



Wheel cover F R, Missing, E - Replace	22,50
---------------------------------------	-------



Steering wheel, Deformed, Acceptable	0,00
--------------------------------------	------



Door moulding Lower R R, Damaged, E - Replace	39,00
---	-------



Reflector, Damaged, Acceptable	0,00
--------------------------------	------

No pictures to display

Trunk door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------



Wheel cover F L, Scratch(es), E - Replace	22,50
---	-------



Door panel F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	22,50
---	-------



Front bumper, Scratch(es), Smart repair	110,64
---	--------



Seat cover F R, Hole, E - Replace

300,00



Bodywork, Not original part, Acceptable

0,00

*No pictures to display*

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

327,15



Door moulding Lower R L, Damaged, E - Replace

39,00



Roof, Damaged, I - Repair

98,00



Rearview mirror housing L, Broken, E - Replace

84,00

