


OPEL Vivaro 2700: 1EJR549

Vinnnumber:	WOLF7A1AFCV647573	Versionname:	VIVARO 2700 B/F L1H1 Ec.DPF(E5)115PK Aut
First Registrationdate:	1/01/2013	Fiscalpower:	
Expertise Mileage:	215632	Power Kw:	85
Bodytype:	Transporter	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2705
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
GPS storage	
GPS storage	SD
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1786,17
-------------------	----------------

Bodywork, Not original part, Acceptable	0,00
-----------------------------------------	-------------

No pictures to display

Foglight R, Crack, E - Replace	115,50
--------------------------------	---------------



Bumper F R, Scratch(es), Smart repair	110,64
---------------------------------------	---------------



Front end, Missing, E - Replace

15,00



Interior, Dirty, Cleaning

75,00



Bumper corner R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)

361,13



Bumper R, Bump(s), E - Replace

329,40




Foglight L, Crack, E - Replace

115,50



Centre console, Hole, E - Replace

104,00



Windscreen, Crack, E - Replace

0,00



Ignition key, Missing, E - Replace 150,00



Trunk door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 410,00

