



MERCEDES C220: 1FRG442

Vinnumber:	WDD2042021G198964	Versionname:	DIESEL
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	60525	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2722
Maintenance:	B5 DANS 175JOURS		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Alarm			
Radio multimedia			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-leather		
Type of climate control:	Autom climate control		
Adaptive cruise control			
Level control			

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear


	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	491,56
--------------------------	---------------

Bonnet, Stone chip(s), Acceptable	0,00
--	-------------



Alloy rim F L, Scratch(es), Acceptable	0,00
---	-------------



Seat cover F L, Damaged, P - Check 0,00



Backrest cover F R, Scratch(es), Smart repair 64,32



Door R L, Bump(s), PDR - Knock out without painting 82,80




Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Door R R, Bump(s), Acceptable 0,00




Ignition key, Incomplete, E - Replace 150,00



Front bumper, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00



Ceiling, Stain, Cleaning 25,00



Alloy rim F R, Scratch(es), Acceptable 0,00

