



|                                            |                          |              |                       |
|--------------------------------------------|--------------------------|--------------|-----------------------|
| VOLKSWAGEN Crafter 35 MWB hoog dak: 033APJ |                          |              |                       |
| Vinnumber:                                 | WV1ZZZ2EZ96033961        | Versionname: | CRAFTER 35 B/F MWB HR |
| First Registrationdate:                    | 20/05/2009               | Fiscalpower: | 88pk                  |
| Expertise Mileage:                         | 160088                   | Power Kwr:   | 65                    |
| Bodytype:                                  | Transporter              | Body color   | Grey                  |
| Gearbox:                                   | MAN 6 VIT                | Paint type   | Metalic               |
| Transmission:                              | Front                    | Rims summer  | Steel                 |
| Fueltype:                                  | Diesel                   | Oil level    | OK                    |
| Battery functioning                        | Yes                      | Parking lot  | LCV15                 |
| Number of doors                            | 5                        |              |                       |
| Number of seats                            | 3                        |              |                       |
| Number head rests                          | 3                        |              |                       |
| Rims summer                                | Steel                    |              |                       |
| Category                                   | Light Commercial Vehicle |              |                       |
| Oil level                                  | OK                       |              |                       |

|                         |                           |               |
|-------------------------|---------------------------|---------------|
| Options                 |                           |               |
| Radio CD                | Type of Tow bar           | Tow bar fixed |
| Windows electric F      |                           |               |
| Cruise Control          |                           |               |
| Type of headlighting    | Headlighting Halogen      |               |
| Type of Lining          | Lining artificial leather |               |
| Type of climate control | Manual climate control    |               |

|                              |     |                     |     |
|------------------------------|-----|---------------------|-----|
| Limited Technical Inspection |     |                     |     |
| Power steering               | Yes | Battery functioning | Yes |
| Airco functioning            | OK  | Sound engine        | OK  |
| Tires wear profile           | OK  | Clutch test         | OK  |
| Idle position                | OK  | Wiper fluid level   | OK  |
| Engine startingtime          | OK  | Lighting            | OK  |
| Exhaust gass                 | OK  | Wiperblades         | OK  |
| Transmission                 | OK  |                     |     |
| Handbrake                    | OK  |                     |     |

|                |                       |                 |       |
|----------------|-----------------------|-----------------|-------|
| Degree of wear |                       |                 |       |
| Winter tyres:  | 235/65/16/115 R Steel |                 |       |
|                | Fr.L.                 | Firestone: 6 mm | Fr.R. |
|                |                       | Firestone: 6 mm |       |
|                | Re.L.                 | Firestone: 7 mm | Re.R. |
|                |                       | Firestone: 7 mm |       |

|                                     |     |      |        |
|-------------------------------------|-----|------|--------|
| Assistance equipment                |     |      |        |
| Spare wheel                         | Yes | Jack | Yes    |
| Total cost ex VAT                   |     |      | 115,50 |
| Model badge R, Missing, E - Replace |     |      | 39,00  |



|                                             |       |
|---------------------------------------------|-------|
| Mirror side blinker R, Damaged, E - Replace | 28,50 |
|---------------------------------------------|-------|



|                                            |      |
|--------------------------------------------|------|
| Sidewall RL (LCV), Scratch(es), Acceptable | 0,00 |
| No pictures to display                     |      |
| Seat cover F L, Worn, Acceptable           | 0,00 |



|                                                    |      |
|----------------------------------------------------|------|
| Trunk door panel R, Chemical pollution, Acceptable | 0,00 |
|----------------------------------------------------|------|



|                            |      |
|----------------------------|------|
| Door F L, Rust, Acceptable | 0,00 |
|----------------------------|------|

No pictures to display

|                                         |      |
|-----------------------------------------|------|
| Bodywork, Not original part, Acceptable | 0,00 |
|-----------------------------------------|------|

No pictures to display

|                                |       |
|--------------------------------|-------|
| Bumper R, Deformed, I - Repair | 48,00 |
|--------------------------------|-------|



|                                |      |
|--------------------------------|------|
| Sill outer R, Rust, Acceptable | 0,00 |
|--------------------------------|------|

