



VOLKSWAGEN Jetta: 1GGT184				
Vinnumber:	WVWZZZ16ZEM026102	Versionname:	JETTA BER 1.6CRTDi	
First Registrationdate:	4/02/2014	Fiscalpower:	Comfort BMT 105PK Aut	
Expertise Mileage:	88432	Power Kw:	77	
Bodytype:	Berline	Body color	Anthracite	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3606	
Number of doors	4			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage	HD	Luggage cover		
GPS storage		Front parking sensors		
Windows electric F		Rear parking sensors		
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Limited Technical Inspection				
Power steering	Yes	Battery functioning	Yes	
Airco functioning	OK	Sound engine	OK	
Tires wear profile	OK	Clutch test	OK	
Idle position	OK	Wiper fluid level	OK	
Engine startingtime	OK	Lighting	OK	
Exhaust gass	OK	Wiperblades	OK	
Transmission	OK			
Handbrake	OK			
Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			241,80	
Wing R R, Bump(s), Acceptable			0,00	
No pictures to display				
Door F L, Bump(s), Acceptable			0,00	
No pictures to display				
Door F R, Bump(s), Acceptable			0,00	
No pictures to display				
Rocker panel inner F R, Scratch(es), Acceptable			0,00	
No pictures to display				
Wheel cover R L, Missing, E - Replace			30,00	



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

