



VOLVO V40: 1JSB975			
Vinnumber:	YV1MV8481F2230573	Versionname:	1.6 D2 KINETIC
First Registrationdate:	11/02/2015	Fiscalpower:	
Expertise Mileage:	112295	Power Kw:	84
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2505
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control


Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		


Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	1142,15
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Bad repair, Paint	0,00
-----------------------------	-------------



Front bumper, Bump(s), LI - Repair and paint (complete)		211,80
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Ignition key, Missing, E - Replace		150,00
No pictures to display		
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		318,35
		
Bumper R, Hole, E - Replace		272,00
		
Bumper R, Bad repair, Paint		0,00
		