


VOLKSWAGEN Golf: 1GA0910

Vinnnumber:	WVWZZZAUZEP051679	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	9/12/2013	Fiscalpower:	
Expertise Mileage:	115945	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2203
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/91 T LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1390,55
-------------------	----------------

Wing R L; Bump(s); PDR - Knock out without painting	63,00
---	--------------



Bumper R, Damaged, Le - Replace and paint	651,00
---	---------------





Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Interior, Dirty, Cleaning

50,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35

