



VOLKSWAGEN Polo: 1ESH215			
Vinnnumber:	WVWZZZ6RZDY183854	Versionname:	POLO Trendline DPF 75PK
First Registrationdate:	7/03/2013	Fiscalpower:	
Expertise Mileage:	61317	Power Kw:	55
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3633
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Summer tyres:	175/70/14/84 T Steel			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment	
Spare wheel	Yes Jack
Total cost ex VAT	25,00
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Rear spoiler, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Scratch(es), Acceptable	0,00
No pictures to display	
Seat cover R L, Stain, Cleaning	25,00



Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F L, Scratch(es), Acceptable	0,00

No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	