



VOLKSWAGEN Golf: 1BVK438

Vinnnumber:	WVWZZZ1KZCW094176	Versionname:	GOLF BER BlueMotion DPF
First Registrationdate:	13/09/2011	Fiscalpower:	105PK
Expertise Mileage:	127119	Power Kw:	77
Bodytype:	Hatchback	Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2313
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Luggage cover
GPS storage	
GPS storage	DVD
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			346,80
Bonnet, Stone chip(s), Acceptable			0,00
No pictures to display			
Wing R R, Scratch(es), Acceptable			0,00
No pictures to display			
Door F L, Scratch(es), Acceptable			0,00
No pictures to display			
Door R L, Scratch(es), Acceptable			0,00
No pictures to display			
Trunk lid covering R, Scratch(es), Acceptable			0,00
No pictures to display			
Door panel F L, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover F R, Scratch(es), E - Replace			30,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 75,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

