



VOLKSWAGEN Golf: 1JFD364

Vinnnumber:	WVWZZZAUZFP044417	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	1/12/2014	Fiscalpower:	
Expertise Mileage:	149138	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1630
Maintenance:	1100KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		


Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	145,56
Wing R R, Bump(s), Acceptable	0,00



Front bumper, Scratch(es), It - Spot repair	115,56
---	---------------



Wheel cover F R, Scratch(es), E - Replace

30,00

