




VOLVO V40: 1EVA144			
Vinnnumber:	YV1MZ8451D2007456	Versionname:	V40 Cr.Country D2 Base 115PK
First Registrationdate:	27/03/2013	Fiscalpower:	
Expertise Mileage:	124111	Power Kw:	84
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3231
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1248,18
Rear window, Scratch(es), E - Replace			370,00



Tailgate, Chemical polution, LI - Repair and paint (complete)	301,68
---	---------------



Armrest R M, Scratch(es), Acceptable 0,00



Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Seat cover F L, Worn, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display