




VOLVO XC60: 1FAY506			
Vinnumber:	YV1DZ31A1D2461219	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	13/05/2013	Fiscalpower:	
Expertise Mileage:	205162	Power Kw:	100
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2425
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	235/65/17/108 V LightMetal			
Winter tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			382,02
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rocker panel inner R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)			382,02



Windscreen, Stone chip(s), Acceptable			0,00
---------------------------------------	--	--	-------------



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display