



## VOLVO XC60: AK8689

Vinnnumber:	<b>YV1DZ87A4C2301430</b>	Versionname:	<b>XC60 D3 AWD Kinetic St/St 163PK</b>
First Registrationdate:	<b>6/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>183615</b>	Power Kw:	<b>120</b>
Bodytype:	<b>SUV</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3403</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

## Limited Technical Inspection

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

## Degree of wear

	<b>235/60/18/107 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 3,5 mm</b>	Fr.R.	<b>Pirelli: 3,5 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	334,00
-------------------	--------

Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Brand badge, Worn, Acceptable	0,00



Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------



Daytime running lights L, Crack, E - Replace	144,00
--	--------

