



**SKODA OCTAVIA COMBI: 1JVC867**

Vinnnumber:	<b>TMBJG7NE7F0173794</b>	Versionname:	<b>1.6 CRTDI 77KW GREENTEC AMBITION</b>
First Registrationdate:	<b>4/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>146636</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2208</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>VS</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric
GPS storage	<b>SD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	
Level control		

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/94 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Firestone: 6 mm</b>	Fr.R.	<b>Firestone: 6 mm</b>
	Re.L.	<b>Firestone: 6 mm</b>	Re.R.	<b>Firestone: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1007,35</b>
<b>Door F L, Bump(s), LI - Repair and paint (complete)</b>	<b>366,35</b>





Seat cover F R, Stain, Cleaning 25,00



Wing R R, Bad repair, P - Check 0,00



Door R R, Bad repair, P - Check 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 259,80



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Wing R L, Bump(s), LI - Repair and paint (complete) 356,20

