



RENAULT Scenic: 1EPJ946

Vinnumber:	VF1JZ140648435543	Versionname:	SCENIC Energ.Expression
First Registrationdate:	14/02/2013	Fiscalpower:	110PK
Expertise Mileage:	98096	Power Kw:	81
Bodytype:		Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3503
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		


Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment










Spare wheel	Yes
-------------	------------

Total cost ex VAT	1878,64
Rearview mirror housing R, Damaged, LI - Repair and paint (complete)	115,56



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display
Bumper corner R R, Scratch(es), It - Spot repair 115,56

		119,00
Radio, Scratch(es), Acceptable		0,00
		
Interior, Dirty, Cleaning		100,00
		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover F R, Scratch(es), E - Replace		30,00
		
Bumper R, Bump(s), Smart repair		110,64
		
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		318,35
		
Door F R, Bump(s), LI - Repair and paint (complete)		318,35
		
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		308,20
		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Wheel cover F L, Scratch(es), E - Replace 30,00

