



RENAULT Scenic: 1ET1985

Vinnumber:	VF1JZ140648617150	Versionname:	SCENIC Energ.Expression
First Registrationdate:	15/03/2013	Fiscalpower:	110PK
Expertise Mileage:	114853	Power Kw:	81
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3710
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1651,91
Outer door handle F L, Scratch(es), Le - Replace and paint			173,00



Centre console, Scratch(es), E - Replace	104,00
---	---------------





Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair 115,56



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), It - Spot repair 115,56




Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20





Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display