



**AUDI A4: 1FL1888**

Vinnumber:	<b>WAUZZZ8K7EA004343</b>	Versionname:	<b>A4 AVANT TDie 136PK</b>
First Registrationdate:	<b>6/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>97903</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1619</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
GPS storage	<b>HD</b>
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/95 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 3 mm</b>	Re.R.	<b>Goodyear: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 2110,40

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Luggage space cover, Missing, E - Replace	240,00
---	--------



Sill outer R, Bump(s), LI - Repair and paint (complete)	310,50
---	--------

