



| AUDI A6 AVANT: 1KPC862 | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber: | WAUZZZ4G8FN091391 | Versionname: | 2.0 TDI ULTRA 100KW |
| First Registrationdate: | 8/06/2015 | Fiscalpower: | |
| Expertise Mileage: | 39794 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3433 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Xenon |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|----------------------------------|--------------------------|-------|--------------------------|
| | 225/60/16/98 H LightMetal | | | |
| Winter tyres: | Fr.L. | Dunlop: 7 mm | Fr.R. | Dunlop: 7 mm |
| | Re.L. | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

| Assistance equipment | |
|-----------------------|------------|
| Emergency spare wheel | Yes |

| | |
|---------------------------------------------------------|--------|
| Total cost ex VAT | 718,88 |
| Wing R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 254,16 |



| | |
|-------------------------------------------------------------------------|--------|
| Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) | 254,16 |
|-------------------------------------------------------------------------|--------|



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display