



AUDI A6: 1ERM174

Vinnnumber:	WAUZZZ4G3DN103556	Versionname:	A6 BER Quat. 5-tr. 204PK Aut.
First Registrationdate:	1/03/2013	Fiscalpower:	
Expertise Mileage:	99881	Power Kw:	150
Bodytype:	Berline	Body color:	Dark Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3409
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage	SD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	190,00
-------------------	---------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------




Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Wing R R, Increased paint layer, No repair		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Bad repair, Paint		0,00
