



AUDI A3: 1HDC666			
Vinnumber:	<b>WAUZZZ8V2EA172241</b>	Versionname:	<b>A3 SB Attraction 105PK</b>
First Registrationdate:	<b>23/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>181856</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>2117</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
GPS storage	<b>SD</b> Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>
Head-up Display	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Fulda: 7 mm</b>	Re.R.	<b>Fulda: 7 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

Total cost ex VAT	231,12
Wing F L, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer L, Bump(s) and scratch(es), It - Spot repair	115,56





Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*

Bonnet, No damage, P - Check 0,00



Bumper F R, Scratch(es), It - Spot repair 115,56



Door R R, Bump(s), Acceptable 0,00

*No pictures to display*

Wing F R, Stone chip(s), Acceptable 0,00

*No pictures to display*

Trunk lid covering R, Scratch(es), Acceptable 0,00

*No pictures to display*

Maintenance, Maintenance, P - Check 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*