


AUDI A6: 1GCS502

Vinnumber:	WAUZZZ4G0EN077676	Versionname:	A6 BER 163PK
First Registrationdate:	2/01/2014	Fiscalpower:	
Expertise Mileage:	175057	Power Kw:	120
Bodytype:	Berline	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3632
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm







Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	929,56
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display		
Door R R, Bump(s), Acceptable		0,00
No pictures to display		
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		369,84
		
		
Wing F L, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper F L, Scratch(es), It - Spot repair		115,56
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		254,16
		
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
