



**BMW 1: 1HPL865**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber:                        | <b>WBA1C710X0J951459</b> | Versionname: | <b>1 BER HATCH 116d 116PK</b> |
| First Registrationdate:            | <b>5/09/2014</b>         | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>201481</b>            | Power Kw:    | <b>85</b>                     |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>White</b>                  |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2605</b>                   |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Rear parking sensors             |
| Cruise Control                 |                                  |
| Steering wheel multifunctional |                                  |
| Radio multimedia               |                                  |
| Type of headlighting:          | <b>Headlighting Halogen</b>      |
| Type of Lining:                | <b>Lining artificial leather</b> |
| Type of climate control:       | <b>Manual climate control</b>    |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/50/17/93 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Uniroyal: 6 mm</b> | Fr.R. | <b>Uniroyal: 6 mm</b> |
|               | Re.L.                            | <b>Uniroyal: 5 mm</b> | Re.R. | <b>Uniroyal: 5 mm</b> |

**Assistance equipment**

|  |        |
|--|--------|
| Total cost ex VAT                      | 120,00 |
| Rear wiper blade, Damaged, E - Replace | 25,00  |



|  |       |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|                                 |      |
|---------------------------------|------|
| Bonnet, Scratch(es), Acceptable | 0,00 |
|---------------------------------|------|