



BMW 3: 1ETE179			
Vinnumber:	WBA3D91090F404574	Versionname:	3 BER 316d 116PK
First Registrationdate:	14/03/2013	Fiscalpower:	
Expertise Mileage:	100916	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2106
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear				
	205/60/16/92 H Steel			
Summer tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1913,59
Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	--------------



Wheel cover F R, Scratch(es), E - Replace 30,00



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 481,50




Wheel cover R L, Scratch(es), E - Replace 30,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

