



AUDI A4: 1DV032			
Vinnumber:	WAUZZZ8K6DA102830	Versionname:	A4 AVANT TDi Multitr.136PK Aut.
First Registrationdate:	7/09/2012	Fiscalpower:	
Expertise Mileage:	130458	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2212
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/55/16/95 H LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Emergency spare wheel	Yes Jack Yes
Total cost ex VAT	2617,68
Wing R L, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Xenon headlight L, Scratch(es), E - Replace	696,00
---	--------



Interior, Dirty, Cleaning 50,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Chemical polution, LI - Repair and paint (complete) 318,35



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Rearview mirror R complete, Damaged, Le - Replace and paint 283,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Windscreen, Repaired, Acceptable 0,00



Door R R, Accident, LI - Repair and paint (complete) 318,35

