


BMW 5: 1GNF784

Vinnumber:	WBA5J11040D336005	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	17/03/2014	Fiscalpower:	
Expertise Mileage:	139228	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2322
Maintenance:	16/11/2017		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	VS		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment









Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2170,81
-------------------	---------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

	Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
	Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
	Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
	Ignition key, Missing, E - Replace	150,00
	<i>No pictures to display</i>	
	Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
	Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
	Bonnet, Stone chip(s), Acceptable	0,00
	<i>No pictures to display</i>	
	Wing R L, Bump(s), PDR - Knock out without painting	63,00
	Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
	Front bumper, Scratch(es), It - Spot repair	115,56
	Alloy rim F L, Scratch(es), Acceptable	0,00
	<i>No pictures to display</i>	