


BMW 318D: 1GCY633

Vinnumber:	WBA3Y11020D448255	Versionname:	DIESEL
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	66129	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1311
Maintenance:	19000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	214,51
-------------------	--------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------



Wing R R, Scratch(es), Acceptable 0,00



Wing F L, Bump(s), Acceptable 0,00



Bonnet, Chemical pollution, 67 - Polish 55,19



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Backrest cover F L, Scratch(es), Smart repair 64,32



Tailgate, Scratch(es), Acceptable 0,00

