


AUDI A4: 1FQD652

Vinnumber:	WAUZZZ8K1EA046135	Versionname:	A4 AVANT TDi 120PK
First Registrationdate:	20/09/2013	Fiscalpower:	
Expertise Mileage:	189898	Power Kw:	88
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Body color:	.
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	DANS 13500 KM	Oil level:	OK
Maintenance:	OK	Parking lot:	2814
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	DVD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/16/95 H LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	682,98
Alloy rim F R, Scratch(es), 1 - Repair	100,00



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Door R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Seat cover F R, Stain, Cleaning	25,00
---------------------------------	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



GPS disc, Not functioning (well), P - Check	0,00
---	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------



Wing R R, Stone chip(s), Acceptable	0,00
-------------------------------------	------

